



(単位 : mm)

呼び名	B	H	$a_1$	$a_2$	c	r	h	d
OPU - 240	930	500	240	220	240	50	140	100
OPU - 300B	1000	550	300	260	300	50	200	100
OPU - 360B	1060	600	360	310	360	50	260	100
OPU - 450	1160	650	450	400	450	70	350	100
OPU - 600	1340	900	600	540	600	70	500	100